Wednesday, 23/04/2008 10:22:23 AM

User:

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number

: 38769

: 23/04/2008

Estimate Number

: 10824

P.O. Number

This Issue

Prsht Rev. First Issue : NC

: //

: LARGE FAB ASSY Type

: 35820 Previous Run

Written By

Checked & Approved By

Comment

: EST. REV. A

EST. REV.C

05.12.19 EST, REV. B

updated pick list 07.11.12 ecn 1019, nochg

verifiedby:DD

Drawing Revision

Material Due Date

EC

EC

Drawing Name

Part Number

Drawing Number

Project Number

: 30/04/2008

: D412630032

: IIN D412-630

: N/A

: L

Qty:

: PILOT/CO-PILOT STEP, RH (FOLDING)

2 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

NEW ISSUE

Description: DOCUMENT CONTROL

1.0

Comment: DOCUMENT CONTROL Photocopy D412-630 bluefile & type labels per PPP412-630-034 CHG001

SMALL FAB 1

-032

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D412-630 p.17

****ensure tension to retract step is 11 to 18 lbs before installing lockwire.****

ED08/07/28

68,08-1

3.0

2.0

D3463042

Step Weldment Assembly



Comment: Qty.:

1.0000 Each(s)/Unit Total:

2.0000 Each(s)

Pick:

Qty

Part Number D3463-042

Description

Step weldment

Total:

4.0

D3443043

2.0000 Each(s)

Strut Weldment Assembly

Pick:

1.0000 Each(s)/Unit

Description

Comment: Qty.:

Qty

Part Number D3443-043

Strut ass'y

Dart Ae	rospace	e Ltd								
W/O:		,	V	VORK ORDER CHA	NGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Ca	itegory:	NCI	R: Yes N	lo DQ/	4 :	_ Date: _	
						QA: N/	C Close	d:	Date: _	
NCR:		W	ORK OR	DER NON-CONFOR	RMANCE	(NCR)				
DATE	STEP	P Description of NC Section A	Corrective Action Section B				Verification		Approval	Approval
			Initial Chief Eng	Action Descripti Chief Eng	ion	Sign & Date	Secti		Chief Eng	QC Inspector

NOTE: Date & initial all entries

Daţe: Wednesday, 23/04/2008 10:22:23 AM Linda Lacelle User: **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Part Number: D412630032 Job Number: 38769 Job Number: Seq. #: Description: **Machine Or Operation:** D3443041 5.0 Strut Weldment Assembly Comment: Qty.: 2.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Qty Part Number Description D3443-041 Strut ass'y 1 D34439 6.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Part Number Description Qty Batch 2 D3443-9 Pin 7.0 AN4CH3 SS Bolt Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Qty Part Number Description **BOLT** 2 AN4CH3 A/R MS20995c41e Lockwire 08-08-13 BOLT AN4C14 8.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Batch /03248 Part Number Description Qty 1 AN4C14 **BOLT** 9.0 D34547 Bushing Comment: Qty.: 4.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: Description Batch · Qty Part Number 35636 2 D3454-7 Bushing

Dart Ae	rospace L	_td								
W/O:	i		W	ORK ORDER CH	IANGES					
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				44.0			······································			
Part No	:	PAR #:	Fault Cate	egory:	NCI				Date:	
NCR:		,	WORK ORD	ER NON-CONFO	ORMANCE					
DATE		Description of NC Section A		Corrective Action Section B			Verifi		Approval	Approval
	STEP		Initial Chief Eng	Action Descri	ption	Sign & Date	Sect			QC Inspector
					:					

NOTE: Date & initial all entries

 Wednesday, 23/04/2008 10:22:23 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Part Number: D412630032 Job Number: 38769 Job Number: Seq. #: Description: **Machine Or Operation:** AN3104 NUT 10.0 Comment: Qty.: 4.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: Qtv Part Number Description 107139 2 AN310-4 Nut 11.0 MS24665227 COTTER PIN Comment: Qtv.: 2.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Qty Description Part Number 106043 MS24665-227 **COTTER PIN** 12.0 D34551 Spacer Comment: Qty.: Total: 4.0000 Each(s) 2.0000 Each(s)/Unit Pick: Qtv Description Part Number 28/71 2 D3455-1 Spacer 13.0 D34651 Washer Comment: Qty.: 2.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Qty Part Number Description 370C Washer D3465-1 1 14.0 AN3107 Comment: Qty.: 2.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Qty Part Number Description AN310-7 Nut 0/4/22

Page 3


Form: rprocess

Wednesday, 23/04/2008 10:22:23 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Job Number: 38769 Part Number: D412630032 Job Number: Seq. #: Description: **Machine Or Operation:** MS24665302 Cotter Pin 15.0 2.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Qty Part Number Description MIDGIBB 1 MS24665-302 COTTER PIN 50 INSPECT WORK TO CURRENT STEP 16.0 QC5 Comment: INSPECT WORK TO CURRENT STEP ****ensure tension to retract step is 11 to 18 lbs **** Test fit on aircraft in Eng. lab. 17.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit D34541 Bushing 18.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Description Qty Part Number 1 D3454-1 Bushing D34543 Bushing Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Qty Part Number Description 2 D3454-3 Bushing 20.0 D34545 Bushing Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Batch 34842 Qty Part Number Description 2 D3454-5 Bushing 8/4/24

Wednesday, 23/04/2008 10:22:23 AM Date: Linda Lacelle User: **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Part Number: D412630032 Job Number: 38769 Job Number: Description: Seq. #: **Machine Or Operation:** 21.0 D34551 Spacer Comment: Qty.: 6.0000 Each(s)/Unit Total: 12.0000 Each(s) Pick: 30226 Qty Part Number Description 2 D3455-1 Spacer D34553 22.0 Spacer Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Description Qty Part Number 2 D3455-3 Spacer D3462042 Bracket Assembly Comment: Qty.: 2.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: 35860 Part Number Description Qty D3462-042 Bracket ass'y 24.0 AN3104 NUT Comment: Qty.: Total: 2.0000 Each(s) 1.0000 Each(s)/Unit Pick: Qty Part Number Description AN310-4 1 Nut 25.0 AN3105 NUT Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Description Qty Part Number 105280 AN310-5 Nut 8/4/24 2

Page 5

Form: rprocess



Date: Wednesday, 23/04/2008 10:22:23 AM Linda Lacelle User: **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Part Number: D412630032 Job Number: 38769 Job Number: **Description:** Seq. #: **Machine Or Operation:** AN960C10 WASHER 31.0 Comment: Qty.: Total: 14.0000 EACH(s) 7.0000 EACH(s)/Unit Pick: Qty Part Number Description Batch 106302 AN960C10 Washer WASHER AN960C516 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Qty Part Number Description Batch AN960C516 Washer MS210433 Nut Comment: Qty.: 3.0000 Each(s)/Unit Total: 6.0000 Each(s) Pick: Qty Part Number Description 3 MS21043-3 Nut MS24665227 **COTTER PIN** 34.0 Comment: Qty.: 4.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: Qty Part Number Description 06043 **COTTER PIN** 2 MS24665-227 35.0 MS24665229 COTTER PIN Comment: Qty.: Total: 4.0000 Each(s) 2.0000 Each(s)/Unit Pick: Part Number Description Qty MP1096 MS24665-229 **COTTER PIN** 2

 Wednesday, 23/04/2008 10:22:23 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: PILOT/CO-PILOT STEP, RH (FOLDING) Customer: CU-DAR001 Dart Helicopters Services Part Number: D412630032 Job Number: 38769 Job Number: Seq. #: Description: **Machine Or Operation:** Washer 36.0 NAS1515H5 Comment: Qty.: 2.0000 Each(1.0000 Each(s)/Unit Total: 11060 Pick: Batch Description Qty Part Number NAS1515H5 Washer OR COMPLETENESS QC4 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE #1 38.0 PACKAGING 1 Comment: PACKAG Identify and pack for shipping as per PPP D412-630-031 Location: PPP Rev: FINAL INSPECTION/W/O RELEASE 39.0 QC21 80180 Comment: FINAL INSPECTION/W/O RELEASE u 8.08.14 Job Completion




FIGURE 23 – Isometric View D412-630-032 RH, Pilot/Co-Pilot Folding-Step Installation (Shown) D412-630-031 LH (Opposite)




FIGURE 24 - Detail Safety Wiring, D412-630-032 RH,Pilot/Co-Pilot Folding-Step Installation (Shown) D412-630-031 LH (Opposite)

• COPYRIGHT @ 1996 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision:

Date:

07.09.30

Qty:

2 Um:

Each

: PILOT/CO-PILOT STEP, RH (FOLDING)

: D412630032

: IIN D412-630

: 30/04/2008

REFERENCE

: N/A

: L

Date:

Wednesday, 28/05/2008 10:11:29 AM

User: 🔏

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

EC

EC

EC

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

: 38769

Job Number **Estimate Number** : 10824

P.O. Number

This Issue

Prsht Rev.

First Issue

Previous Run

: 28/05/2008

: NC

: 23/04/2008

: 35820

Written By

Checked & Approved By

Comment

: EST. REV. A

EST. REV. B 05.12.19

EST. REV.C 07.11.12

05.11.21

updated pick list ecn 1019, nochg

NEW ISSUE

: SMALL /MED FAB

verifiedby:DD

Additional Product

Seq. #:

Job Number:

Machine Or Operation:

Description:

1.0 DC

DOCUMENT CONTROL

Comment: DOCUMENT CONTROL

Photocopy D412-630 bluefile & type labels per PPP412-630-031 CHG001

2.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per dwg D412-630 p.17

****ensure tension to retract step is 11 to 18 lbs before installing lockwire.****

3.0

D3463042

Step Weldment Assembly



Comment: Qty.:

1.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

Qty

Part Number

Description

Batch

1 D3463-042 Step weldment

4.0

D3443043

Strut Weldment Assembly

Comment: Qty.: 1.0000 Each(s)/Unit Total:

2.0000 Each(s)

Pick:

Qty

Part Number

Description Strut ass'y

Batch

1

D3443-043